

Last Part Duties > Director

- Specialist Asbestos Removal and environmental clean up- Fire protection work.
- Experience of working on petrochemical sites.



FUNCTIONS AND RESPONSABILITIES

- Manage Finance and Annual Report
- Preside over legal matters and litigations
- Sites visit<News> ensure the technicality and risks
Oversee the establish procedures and the removal plan
Oversee quotes and contracts documentation
- Sites visit<as progress works >ensure all sites are conform to the certificate in all aspects And perform to the exigencies of the contract
- Ensure health and safety environment are in compliance

TECHNICAL KNOW HOW –Asbestos removal – Asbestos encapsulation.

-Removal of existing fire protective coating,

-DÉSAMIANTAGE - TRAITEMENT DE SURFACE DES SOLS-

- Internal quality document management
- Staff organisation
- Materials and equipment management
- Technical procedures Asbestos and other
- Risk Analysis
- Confinement installation on site
- Individual protection
- First aid organisation on site
- Entrances en zone installation
- Access control
- Asbestos handling technique
- Waste management
- Dust control
- Decontamination and break up of site
- Claims and complaints
- Internal audits

Particulars references <France only>

- LES 4 TEMPS LA DEFENSE<Asbestos removal>
- TOUR AUZONE<Asbestos removal>
- Centre Commercial «Les 3 Fontaines»
- GERIC CONTINENT a THIONVILLE (57)CASERNE « PAJOL » MONTBELIARD
- Groupe Scolaire des Glycines
- Chantier de l'ancienne chaufferie Peaudouce<Asbestos removal>
- DARTY MONTPARNASSE<Asbestos removal>
- Ancienne Usine EVERITE809, Rue du Port-77190 DAMMARIE LES LYS< Dépose de 58 000 M2 de plaques amiante sur différents buildings<Asbestos removal>

TECHNICAL KNOW HOW –Fire protection /hydrocarbon fire resistance

Application fire protective coating in accordance with the manufacturers written instructions for application, and in accordance with all relevant Engineering Specifications.< Fendolite MII vermiculite cement system>

- USINE DE CHOQUES< IGNIFUGE 4 REACTEURS>TOTAL GAS

